



Gilbert House
406 Roding Lane South
Woodford Green
Essex, IG8 8EY
United Kingdom

Job or Identification Number	PARIS C3 HX15	Date	14/07/2015 14:22
Location / Sample Designation	TEST ROOM	Operator	Ray Smith
		Temperature	18

Rz Surface Microroughness Readings

1	2	3	4	5	6	7	8	9	10	Mean

Pendulum Serial Number	1519	Calibration Date	26/05/2016 14:22
Slider Rubber Used	Slider 55 Slider 96	Level	0 Zero 0
Slider Preparation, P400 & lapping film	Green Pink		

Verification
readings (PTV)

lapping film test	55 , 60 , 59 / 60 , 60 , 59 , 59 , 59
float glass test	8 , 7 , 7 / 7 , 7 , 7 , 7 , 7
Pavigres tile test	36 , 36 , 35 / 35 , 35 , 35 , 35 , 34

Median
59
7
35

Floor Description	MATT TILE
Floor Condition	AS FOUND
	Slope 0

Pendulum Readings

Direction	Condition	Contamination	Readings	Median
STRAIGHT	WET	WATER	39 , 39 , 39 / 39 , 39 , 38 , 38 , 38	38
ACROSS	WET	WATER	37 , 37 , 37 / 37 , 37 , 37 , 37 , 37	37
DIAGONAL	WET	WATER	37 , 36 , 37 / 37 , 37 , 37 , 37 , 37	37
DIAGONAL	DRY	NONE	60 , 64 , 63 / 62 , 62 , 61 , 61 , 61	61
STRAIGHT	DRY	NONE	61 , 62 , 61 / 61 , 61 , 61 , 57 , 61	61
ACROSS	DRY	NONE	61 , 61 , 61 / 61 , 60 , 60 , 60 , 60	60