



Gilbert House
406 Roding Lane South
Woodford Green
Essex, IG8 8EY
United Kingdom

Job or Identification Number	PARIS C2 HX31	Date	14/07/2015 14:22
Location / Sample Designation	TEST ROOM	Operator	Ray Smith
		Temperature	18

Rz Surface Microroughness Readings

1	2	3	4	5	6	7	8	9	10	Mean

Pendulum Serial Number	1519	Calibration Date	26/05/2016 14:22
Slider Rubber Used	Slider 55 Slider 96	Level	0 Zero 0
Slider Preparation, P400 & lapping film	Green Pink		

Verification
readings (PTV)

lapping film test	55 , 60 , 59 / 60 , 60 , 59 , 59 , 59
float glass test	8 , 7 , 7 / 7 , 7 , 7 , 7 , 7
Pavigres tile test	36 , 36 , 35 / 35 , 35 , 35 , 35 , 34

Median
59
7
35

Floor Description	MATT TILE
Floor Condition	AS FONUD
	Slope 0

Pendulum Readings

Direction	Condition	Contamination	Readings	Median
STRAIGHT	WET	WATER	32 , 30 , 30 / 29 , 29 , 29 , 28 , 28	29
ACROSS	WET	WATER	31 , 29 , 29 / 29 , 29 , 28 , 28 , 28	28
DIAGONAL	WET	WATER	30 , 29 , 29 / 29 , 28 , 28 , 28 , 28	28
DIAGONAL	DRY	NONE	63 , 59 , 59 / 59 , 58 , 59 , 58 , 58	58
ACROSS	DRY	NONE	58 , 59 , 59 / 58 , 58 , 58 , 58 , 57	58
STRAIGHT	DRY	NONE	56 , 57 , 57 / 57 , 57 , 57 , 57 , 57	57